Model name making explanation

S	S	W	9	7	3	4	L	W	P

: -
P : POP nut spec (only refer to 9type motor)
2 : 97 LS & LM style: two fixing holes

E : 95 96 type (standard)
L : 98 9V type(standard)
LS : 97 type（single magnet)
LM : 97 type(single magnet with high torque)
LW : 97 type (double magnets)

Serial number of same model

X=
8: Bracket: - ultra-thin, can resist under condition of below 80W&400g
7: Bracket - Harness position face backward
6: Bracket - Harness position face down, three fixing holes
5: Bracket - Harness position face down, two fixing holes
V: Bracket - JIS D0203 D1 spec, submerged motor

10 : Armature size 10cm -- Four wheel(Made in Japan)
9X :Armature size 9cm -- Four wheel or two wheel
71 :Armature size 7cm -- Two wheel
61 :Armature size 6cm -- Two wheel
PS: Flat motor's out put power depends on armature size,
if armature size is big, output power will be also big.

SSW : Panasonic Automative DC falt motor